

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080146-2 No. 11543


2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 3-8-57

P.O. NO.

VENDOR PACKING SLIP NO.

| CHARGE TO QUANTITY RECEIVED | CONTRACT CODE NO. | DRAWING NUMBER | DWG. DASH OR STANDARD PART NO. | DWG. REV. | LOT NO. | CLASS NUMBER | OPER. NUMBER | BUY OUT CODE NO. | ACCT. OR W.O. NO. S.O. NO. |
|---|-----------------------------|-------------------|-----------------------------------|--------------|------------|-----------------|-----------------|---------------------|----------------------------------|
| | DRAWING NO. AND DESCRIPTION | | | | | | | | |
| 6 | 322 | | 3 | 0 | 21 | | | | |
| 738304 Gear Shaft Assy | | | | | | | | | |
| IP# 704722 | | | | | | | | | |
| To supersede Rec. Insp. report #11524 | | | | | | | | | |
| <div style="text-align: right;">  </div> | | | | | | | | | |

RECEIVED BY *J. B. Carlos* INSPECTED BY *Dura* DATE 3/11/57 REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.


No. 11555

RECEIVED FROM

DATE REC'D. 3-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

| CHARGE TO QUANTITY RECEIVED | CONTRACT CODE NO. | DRAWING NUMBER | DWG. DASH OR STANDARD PART NO. | DWG. REV. | LOT NO. | CLASS NUMBER | OPER. NUMBER | BUY OUT CODE NO. | ACCT. OR W.O. NO. S.O. NO. |
|---|-----------------------------|-------------------|-----------------------------------|--------------|------------|-----------------|-----------------|---------------------|----------------------------------|
| | DRAWING NO. AND DESCRIPTION | | | | | | | | |
| 63 | 322 | | 015 | 0 | 21 | | | | |
| 738225-1 Flange Assy Spool | | | | | | | | | |
| IP# 704732 | | | | | | | | | |
| <div style="text-align: right;">  </div> | | | | | | | | | |

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080146-2

RECEIVED BY *J. B. Carlos* INSPECTED BY *Dura* DATE 3/12/57 REJECTS RETURNED ON SHIP. MEMO NO.